

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Kollé et al. Attorney Docket No. TEMP0011
 Patent No: 7,139,219 Group Art Unit: 3672
 Issued: November 21, 2006 Examiner: Stephenson, Daniel P.
 Title: HYDRAULIC IMPULSE GENERATOR AND FREQUENCY SWEEP
 MECHANISM FOR BOREHOLE APPLICATIONS

NOTIFICATION OF ERRORS

Bellevue, Washington 98004

January 19, 2007

TO THE COMMISSIONER FOR PATENTS:

The following errors were found during a review of the above-referenced United States Letters Patent. These errors were either inadvertently made in the original application or occurred in the printing of the patent. Since the errors are of an obvious nature, a formal Certificate of Correction is not believed to be warranted at this time. Therefore, it is requested that this notification be placed in the U.S. Patent and Trademark Office file.

<u>Location in Patent</u>	<u>Error</u>
Column 26, line 12	“boreholes;,” should read --boreholes;--
Column 29, line 2	“know” should read --known--
Column 29, line 37	after “examples” insert --of--
Column 32, line 50	“though” should read --through--
(Claim 21, line 2)	

Respectfully submitted,

/mike king/
 Michael C. King
 Registration No. 44,832